

# **APPENDIX H**

## **PHOTOS OF IMPROVEMENTS**






**Daylodge looking southwest.**



**Lodge looking northwest.**



**Garage building front and east side looking northwest.**



**Maintenance building front and east end looking northwest.**



**Maintenance building interior.**



**West lift lower terminal looking north.**



**West lift line looking uphill (south) from the base.**



**East chairlift bottom terminal looking east.**



**East lift line looking downhill (north) from near the top terminal.**